

Итоги мониторинга «опасных» объектов

№ п/п	Выявленные недостатки	Наименование объекта	Фотоматериалы
1	<p>объект не функционирует, работы по сносу не завершены, отсутствует ограждение</p>	<p>банно-прачечный комплекс ОАО «Дуброво-2013»</p>	





2

объект не функционирует, отсутствует ограничение доступа, люки технических колодцев не закрыты, подземный резервуар для хранения мазута не закрыт

территория и комплекс неэксплуатируемых зданий ООО «Интернэшнл Пластик» Олехновичский сельисполком д. Дуброво



			 <p>The top photograph shows a brick wall with a large, irregular hole. The hole is filled with a pile of rubble, including bricks and stones. The area is surrounded by dense green foliage and trees. The bottom photograph shows a manhole cover in a grassy yard. The cover is made of dark material and is surrounded by grass and some weeds. A small, light-colored object is visible near the cover.</p>
--	--	--	--

			
3	<p>объект не функционирует, не приняты меры по ограничению доступа, существует угроза обрушения строительных конструкций</p>	<p>Территория и комплекс зданий ООО «Скваер-плюс»</p>	

--	--	--



